

Laboratory Risk Assessment

KEYS to symbols used on C.O.S.H.H tables

Control Measures

F/C	Fume cupboard must be used
PPE	Personal protective equipment

Small Spillages (volatile substances)

- ?? Shut off all sources of ignition Wear appropriate protective gear from other spillages keep at a safe distance
- ?? Absorb onto Spill granules.
- ?? Sweep into suitable labelled container
- ?? Dispose of via College facilities

Small Spillages

