

Assessment for C.O.S.H.H.

Procedure	Determination of Particle size
------------------	--------------------------------

Substance/Procedure	Risk of exposure * L/M/H	HSE Exposure Limits (mg/m ³)	Local controls used	Disposal	Emergency procedures
Hydrogen peroxide	L	1.5	F/C, PPE, DG,	A, B	1, 4, 6
Calgon	No	Hazards	Listed		

* Risk of exposure providing local controls are .056 Tc 0i590.4 0.6 0.6 re f6 Tw 6s 0 T7j 0 -13.8